

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)
PETER D. SAUNDERS) : Examiner: Danh C. Le
Appln. No.: 10/711,970) : Art Unit: 2617
Filed: October 15, 2004) : Conf. No.: 5969
For: SYSTEM AND METHOD FOR)
REMOTELY INITIALIZING RF) :
TRANSACTION) :
U.S. Patent No.: 7,228,155 B2)
Issued: June 5, 2007) : November 2, 2007

Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CERTIFICATE OF CORRECTION
UNDER RULES 322 AND 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the Patent and Trademark Office due to errors which appear in the printed patent as a result of Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the Patent and Trademark Office. A Certificate of Correction form, in duplicate, is enclosed.

The amount of \$100.00 to cover the statutory fee for such Certificate of Correction is being paid concurrently; please charge any deficiency in the fee, and credit any overpayment, to Deposit Account 06-1205.

Patentee's undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,



Jonathan Berschadsky
Attorney for Patentee
Registration No. 46,551

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
Facsimile: (212) 218-2200

FCHS_WS 1716368v1

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,228,155 B2

DATED : June 5, 2007

INVENTOR(S) : PETER D. SAUNDERS

Page 1 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON THE TITLE PAGE [56] REFERENCES CITED:

U.S. Patent Documents, "5,239,654 A 8/1993 Ing Simmons et al."
should read --5,239,654 A 8/1993 Ing-Simmons et al.--; and
Other Publications,
after "Magic Wands": "BobBrewin" should read --Bob Brewin--,
after "Security for": "relased of" should read --released a--, and
after "TI": "Embarces" should read --Embraces--.

COLUMN 4:

Line 14, "subpart" should read --subpart of--; and
Line 23, "adjacent" should read --adjacent to--.

COLUMN 6:

Line 57, "of" (first occurrence) should read --of a--.

COLUMN 7:

Line 10, "combination" should read --combinations--.

COLUMN 8:

Line 48, "device 102" should read --reader 104--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,228,155 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

Staple
Here
Only!

PRINTER'S TRIM LINE

PATENT NO. : US 7,228,155 B2

DATED : June 5, 2007

INVENTOR(S) : PETER D. SAUNDERS

Page 2 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 9:

Line 15, "POS 112" should --POS device 110--.

COLUMN 11:

Line 20, "a" should read --an--;

Line 32, "3"x4"" should read --3'x4'--; and

Line 65, "eventually" should read --eventually be--.

COLUMN 12:

Lines 46-47, delete "when it is in a rolled position (not shown). The laminate 15 roll".

COLUMN 14:

Line 47, "circuitry 216" should read --circuitry 210--; and

Line 50, "circuitry 216" should read --circuitry 210--.

COLUMN 15:

Line 11, "reader 104" should read --reader 104--; and

Line 18, "ISO/IEC 14443-2" should read --ISO/IEC 14443-2--.

COLUMN 16:

Line 44, "160 standards," should read --ISO standards,--; and

Line 52, "use" should be deleted.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,228,155 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,228,155 B2

DATED : June 5, 2007

INVENTOR(S) : PETER D. SAUNDERS

Page 3 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 17:

Line 27, "transpon- " should read --transporter--;

Line 28, "der" should be deleted; and

Line 35, "202" should read --502--.

COLUMN 18:

Line 61, "user" should read --user's--.

COLUMN 19:

Line 7, "square" should read --square---;

Line 23, delete "logo," (first occurrence); and

Line 26, "module 20," should read --module 20--.

COLUMN 20:

Line 48, "phone 1402." should read --phone 300--.

COLUMN 21:

Line 2, "module 20" should read --module 20,--;

Line 5, "device 1508" should read --device 102--; and

Line 21, "an" should read --and--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,228,155 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,228,155 B2

DATED : June 5, 2007

INVENTOR(S) : PETER D. SAUNDERS

Page 4 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 23:

Lines 46-47, delete "RF module 20 of FIG. 18 may have similar description as module 300."

COLUMN 24:

Line 21, "is" should read --are--;
Line 51, delete "and"; and
Line 52, delete "to" (first occurrence).

COLUMN 25:

Line 1, "(e.g.," should read --(e.g., mobile phone--; and
Line 63, "decryption" should read --decrypt--.

COLUMN 26:

Line 54, "application" should read --application,--; and
Line 55, delete "on".

COLUMN 27:

Line 32, "stand alone" should read --stand-alone--;
Line 42, "does" should read --do--; and
Line 50, "a" should read --an--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,228,155 B2

No. of add'l. copies
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO. : US 7,228,155 B2

DATED : June 5, 2007

INVENTOR(S) : PETER D. SAUNDERS

Page 5 of 5

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 28:

Line 67, "stand alone" should read --stand-alone--.

COLUMN 29:

Line 44, "database 214" should read --database 212--.

COLUMN 31:

Line 5, "controller 314." should read --controller 2108.--; and
Line 7, "encryption decryp-" should read --encryption/decryp---.

COLUMN 32:

Line 50, delete "device".

COLUMN 34:

Line 5, "a" should read --an--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO
30 Rockefeller Plaza
New York, New York 10112-3801
(212) 218-2100 - Telephone
(212) 218-2200 - Facsimile

PATENT NO. US 7,228,155 B2

No. of add'l. copies
@ 30¢ per page

